



ALC Output to R13 POT Gray

To LV Bias & Control PCB Yel/Blk

RF Input from RF I/O PCB Coax

Coax Shield

Coax Shield

RF Input from 4-1 Xfmr Coax

From LV Bias & Cntrl PCB Org

From LV Bias & Cntrl PCB Wht/Org